I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450, on

hi Howard

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Serial No.:

10/074,833

Filed:

February 13, 2002

Patent No.:

6,733,158 B2

Issued:

May 11, 2004

Applicant(s):

Jerry F. Fischer and John Boyer

Title:

WIRING BOX FOR A LUMINAIRE ASSEMBLY

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450 of Correction

ATTN:

DECISION AND CERTIFICATE OF CORRECTION BRANCH OF THE PATENT ISSUE DIVISION

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR PTO MISTAKE (37 CFR §1.322 (a))

Sir:

Attached in duplicate form, is Form PTO-1050, with at least one copy being suitable for printing. The errors which appear in the Form PTO-1050 were typographical errors which occurred through the fault of the U.S. Patent and Trademark Office ("PTO").

The exact column and line number where the errors are shown in the patent are as follows:

Column 4, Lines 64-65 read, "...outwardly from each side wall 38, and a pair of spaced end wails 44 extend away from the planar wall 36 along opposite..." and should read – ... outwardly from each side wall 38, and a pair of spaced end walls 44 extend away from the planar wall 36 along opposite... –.

Column 6, line 30 reads "...86 (FIG., 5) or other connector hardware (not shown) known..." and should read – ...86 (FIG. 5) or other connector hardware (not shown) known... –.

Column 7, line 16 reads "...transverse to the top panel 68. A fastener 118 (FIG., 4) may..." and should read — ...transverse to the top panel 68. A fastener 118 (FIG. 4) may... —.

Column 10, Claim 1, lines 2-3 read "1. An assembly for use in a luminaire, comprising; a ballast housing; and..." and should read – 1. An assembly for use in a luminaire, comprising: a ballast housing; and... –.

Column 10, Claim 11, lines 46-47 read "11. An assembly for use in a luminaire, comprising; a ballast housing including at least on opening formed..." and should read – 11. An assembly for use in a luminaire, comprising: a ballast housing including at least on opening formed... –.

Column 12, Claim 37, line 50 reads "...a fastening member operatively connected to amid ballast..." and should read – ...a fastening member operatively connected to said ballast... –.

Column 12, Claim 38, line 62 reads "...includes a tap panel, a pair of side panels, and a pair of end..." and should read — ...includes a top panel, a pair of side panels, and a pair of end... —

Column 14, Claim 48, line 7 reads "...includes a tap panel, a pair of side panels, and a pair of end..." and should read – ...includes a top panel, a pair of side panels, and a pair of end... –.

Please send the certificate to:

Donald F. Frei, Esq. Wood, Herron & Evans, L.L.P. 2700 Carew Tower Cincinnati, Ohio 45202

If there is any charge or credit due, please use Deposit Account No. 23-3000.

Respectfully submitted,

WOOD, HERRON & EVANS, L.L.P.

Donald F. Frei, Reg. No. 21,190

WOOD, HERRON & EVANS, L.L.P. 2700 Carew Tower Cincinnati, Ohio 45202 (513) 241-2324

Printer's Trim Line

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,733,158 132

DATED : May 11, 2004

INVENTOR(S): Jerry F. Fischer and John Boyer

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 4, lines 64-65 read, "...outwardly from each side wall 38, and a pair of spaced end wails 44 extend away from the planar wall 36 along opposite..." and should read – ...outwardly from each side wall 38, and a pair of spaced end walls 44 extend away from the planar wall 36 along opposite... –.

Column 6, line 30 reads "...86 (FIG., 5) or other connector hardware (not shown) known..." and should read – ...86 (FIG. 5) or other connector hardware (not shown) known... –.

Column 7, line 16 reads "...transverse to the top panel 68. A fastener 118 (FIG., 4) may..." and should read – ...transverse to the top panel 68. A fastener 118 (FIG. 4) may... –.

Column 10, Claim 1, lines 2-3 read "1. An assembly for use in a luminaire, comprising; a ballast housing; and..." and should read – 1. An assembly for use in a luminaire, comprising: a ballast housing; and... –.

Column 10, Claim 11, lines 46-47 read "11. An assembly for use in a luminaire, comprising; a ballast housing including at least on opening formed..." and should read – 11. An assembly for use in a luminaire, comprising: a ballast housing including at least on opening formed... –.

Column 12, Claim 37, line 50 reads "...a fastening member operatively connected to amid ballast..." and should read – ...a fastening member operatively connected to said ballast... –.

Column 12, Claim 38, line 62 reads "...includes a tap panel, a pair of side panels, and a pair of end..." and should read — ...includes a top panel, a pair of side panels, and a pair of end... —.

Column 14, Claim 48, line 7 reads "...includes a tap panel, a pair of side panels, and a pair of end..." and should read – ...includes a top panel, a pair of side panels, and a pair of end... –.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,733,158
No. of add'l copies

@ 50¢ per page:

Wood, Herron & Evans, L.L.P. 2700 Carew Tower 441 Vine Street Cincinnati, OH 45202-2917 Printer's Trim Line

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,733,158 B2

DATED : M

: May 11, 2004

INVENTOR(S): Jerry F. Fischer and John Boyer

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 4, lines 64-65 read, "...outwardly from each side wall 38, and a pair of spaced end wails 44 extend away from the planar wall 36 along opposite..." and should read – ...outwardly from each side wall 38, and a pair of spaced end walls 44 extend away from the planar wall 36 along opposite... –.

Column 6, line 30 reads "...86 (FIG., 5) or other connector hardware (not shown) known..." and should read – ...86 (FIG. 5) or other connector hardware (not shown) known... –.

Column 7, line 16 reads "...transverse to the top panel 68. A fastener 118 (FIG., 4) may..." and should read – ...transverse to the top panel 68. A fastener 118 (FIG. 4) may... –.

Column 10, Claim 1, lines 2-3 read "1. An assembly for use in a luminaire, comprising; a ballast housing; and..." and should read – 1. An assembly for use in a luminaire, comprising: a ballast housing; and... –.

Column 10, Claim 11, lines 46-47 read "11. An assembly for use in a luminaire, comprising; a ballast housing including at least on opening formed..." and should read – 11. An assembly for use in a luminaire, comprising: a ballast housing including at least on opening formed... –.

Column 12, Claim 37, line 50 reads "...a fastening member operatively connected to amid ballast..." and should read – ...a fastening member operatively connected to said ballast... –.

Column 12, Claim 38, line 62 reads "...includes a tap panel, a pair of side panels, and a pair of end..." and should read — ...includes a top panel, a pair of side panels, and a pair of end... —.

Column 14, Claim 48, line 7 reads "...includes a tap panel, a pair of side panels, and a pair of end..." and should read – ...includes a top panel, a pair of side panels, and a pair of end... –.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,733,158
No. of add'l copies
@ 50¢ per page:

Wood, Herron & Evans, L.L.P. 2700 Carew Tower 441 Vine Street Cincinnati, OH 45202-2917